Ja 9 or sooner Work Order ID 76650 *76650* Page 1 November-18-11 10:39:26 AM D3267-043 Item ID: Accept *N900040100* Setup Start **Revision ID:** Item Name: Basket Lid Assembly (Inside) **Start Date:** 18/11/2011 Start Qty: 1.00 Cust Item ID: Req'd Qty: 1.00 **Required Date:** 09/12/2011 **Customer:** Reference: Run Start Process Plan: MI. J Date: 11/11/18 Tooling: **Approvals:** Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ **Operation** Set Up/ Tool ID Tool # Plan Accept Reject Reject Insp. **Work Center ID Description** Qty **Run Hours** Code **Qty** Number Stamp **Draw Nbr Revision Nbr**

100

Weld per dwg A/R S.S. rod Batch: MU57-78 0.00

100

Large Fab

Memo

Rev C

Large Fab Large Fab

D3267

1-Cut Rib from 3/4" x 3/4" x 0.063" wall 304/316 SS tubing as per Dwg D3267

0.00

2-Cut (4) D2236-1 From D3166-3

3-Drill holes in tubing D3267-043 as per Dwg D3267

4-Deburr & Remove All Markings From Material

5-Weld D3267-043. Assembly using Welding Table and corner Jig as per Dwg D3267. Deburr as required

Note: Expanded metal "diamonds" must run lengthwise, Eg 2.0" along length of

SS 11/11/07 (12)

D	art	Aer	os	pac	e Ltd	

		WC	RK ORDER CHANG	ES				
STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	V Constitution of the Cons							
			59		•			
:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA :		_ Date: _	
· · · · · · · · · · · · · · · · · · ·		Disposition	1:	_ QA: N/C Cld	osed:		Date:	·
		WORK ORD	R NON-CONFORMA	NCE (NCR)			
STEP	Description of NC						Approval	Approval
0.2.	Section A	Chief Eng	Action Description Chief Eng	Date	Section	ı C	Chief Eng	QC Inspector
							÷	
								·
								į
							,	٠
								·
								·
	:	PAR #:PAR #:	STEP PROCEDURE CHAR PROCEDURE CHAR PAR #: Fault Category Resolution: Disposition WORK ORDE STEP Description of NC Section A Initial	STEP PROCEDURE CHANGE PAR #: Fault Category: Resolution: Disposition: WORK ORDER NON-CONFORMA STEP Description of NC Section A Section Section A Section A Section Description	PAR #: Fault Category: NCR: Yes Resolution: Disposition: QA: N/C Ck WORK ORDER NON-CONFORMANCE (NCR STEP Description of NC Section A Initial Action Description Sign &	STEP PROCEDURE CHANGE By Date PAR #: Fault Category: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Corrective Action Section B Section A Section A Section Section B Section A Section B	STEP PROCEDURE CHANGE By Date Qty Disposition: NCR: Yes No DQA: NCR: Yes No DQA: Resolution: Disposition: QA: N/C Closed: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC	STEP PROCEDURE CHANGE By Date Qty Chief Eng./ Prod Mgr Disposition: NCR: Yes No DQA: Date: Resolution: Disposition: QA: N/C Closed: Date: WORK ORDER NON-CONFORMANCE (NCR) STEP Description of NC Section A Initial Action Description Sign & Section C Section C Section C Section C Chief Eng./ Prod Mgr Approval Chief Eng./ Prod Mgr

Work Orde			1-	*766	350*						Page 2
Item ID: Revision ID:	D3267-043			Accept	*N900	040	100)* 5	Setup Stai	1.71	S1*
Item Name: Start Date: Required Date: Reference:	18/11/2011	sembly (Inside) Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item I Customer:	D:				* *N	S2*
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):		ate:		Į	Run Star Stoj	" [\]	R1* R2*
Sequence ID/ Work Center II)	Operation Description QC9- Inspect visual per G	OSI004- Fusion Welds	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
110 QC Quality Control		Memo	2000 1 1 20 00 1 1 20 00		fol 11.1:	2.0	7	14	Ø		
120 *120*		QC6- Inspect dimensions	s to drawing	0.00	110						
QC		Memo		0.00	11200						

Quality Control

Dart Aerospace Ltd W/O: **WORK ORDER CHANGES** Approval **Approval** DATE **PROCEDURE CHANGE** By **STEP** Qty Date Chief Eng / QC Inspector Prod Mgr Part No: ______ PAR #: ____ Fault Category: _____ NCR: Yes No DQA: ____ Date: ____ Resolution: _____ Disposition: ____ QA: N/C Closed: ____ Date: ____ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification **Approval Approval** DATE **STEP** Sign & **Action Description** Initial Section C Chief Eng QC Inspector Section A Date Chief Eng Chief Eng

Work Ord November-18-			}-	*766	350*				Page 3
Item ID: Revision ID:	D3267-043			Accept	*N90004	4 010 0*	: Setup	Start	*NS1*
Item Name:	Basket Lid A	ssembly (Inside)						Stop	*NS2*
Start Date: Required Date	18/11/2011 e: 09/12/2011	Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:				
Reference:							Run	Start	*NID4*
Approvals:	Process Pla	an:	Date:	Tooling:	Date:			Stop	"NRT"
	QC:		Date:	SPC (Y/N):	Date:			Stop	*NR2*
Sequence ID/ Work Center 1	I D	Operation Description		Set Up/ Run Hours	Tool ID To	ool # Plan A Code Q		-	Reject Insp. Number Stamp
*130 *130* Powdercoat Powder Coating	,480	IST START TIN OVEN TEN FINISH TIN ********* 2ND COAT START TIN	ME: ME: MPERATURE: ME: ME: ME: ME: ME: ME: ME: ME: ME: M	0.00 0.00 5.1) as per QSI 005 4.3 0.00 4.3 0.00	*****	l×),	M-	L1412/0
140 *140* QC Quality Control		QC3- Inspect Part Finish Memo	1	0.00			B	1/1	2/090

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANGE	ES ,				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							:		
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Disposition	n:	QA: N/C Cld	sed:		Date:	·
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		Corrective Action Section		Verific		Approval	Approval
DAIL	SILI	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector

Work Orden			₹ 7	*766	350*				Page 4
Item ID: Revision ID:	D3267-043			Accept	*N900040	100*	Setup	Start Stop	*NS1*
Item Name: Start Date: Required Date: Reference:	18/11/2011	sembly (Inside) Start Qty: 1.00 Req'd Qty: 1.00	*1* *1*		Cust Item ID: Customer:				*NS2*
Approvals:	Process Pla	n:	Date:	Tooling: SPC (Y/N):	Date:		Run	Start Stop	*NR1* *NR2*
Sequence ID/ Work Center II 145 *145* Packaging Packaging		Operation Description Identify as per dwg & Stoo Memo	ck Location: 6 A W0 76641	Set Up/ Run Hours 0.00	Tool ID Tool #	Plan Acc Code Qty	cept Rejo		Reject Insp. Number Stamp
150 *150* QC Quality Control		QC21- Final Inspection - V	Work Order Release	0.00		(CK 1	<u>. L</u> (<u>:</u>	2/09

WILLES

Dart	Aer	osp	ace	Ltd

W/O:			WO	RK ORDER CHANG	iES			_		
DATE	STEP	PR	OCEDURE CHAN	IGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		·								
e [*]										
Part No	Part No: PAR #:		Fault Categ	ory:	_ NCR:	Yes	No DQ/	\ :	Date:	
	Resolution:		Disposition	:	_ QA: N	VC CIO	sed:		Date:	
NCR:		-	WORK ORDE	R NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of NC			ion B	Sign &	Verific		Approval	Approval
	0.2.	Section A	Initial Chief Eng	Action Description Chief Eng		Date	Section	on C	Chief Eng	QC Inspector
				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1						
					- 1					

Component Item ID/ Item Name D3166-3 ** Basket Hoop Location Loc Qty Loc Code WA 73627 WA007 0.07270527 64928 0.02010527 68442 0.0526 Manufactured No 100 Each 6.0000 *D3182-1* ** Location Loc Qty Loc Code WA 6 71223 6 D3442-3 100 11.0000 Manufactured No Each *D3442-3* ** Location Loc Qty Loc Code WA005 11 70671 11

Dart Aerospace Ltd

W/O:			W	ORK ORDER CHANG	GES			-		
DATE	STEP	PR	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				·						
Part No	•	PAR #:	Fault Cate	gory:	NCR	: Yes	No DQ	A :	Date:	
	Re	solution:	Dispositio	n:	QA:	N/C Cld	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORM	IANCE	(NCR)			
DATE	STEP	Description of NC Section A	Description of NC Corrective Action Section A Initial Action Desc		Section B on Sign &		Verific Section		Approval Chief Eng	Approval QC Inspector
A-00-00-00-00-00-00-00-00-00-00-00-00-00		Coolion	Chief Eng	Chief Eng		Date				

Picklist Print November-18-11 10:39:30 AM	1.						Page 2
Work Order ID: 76650		*7665					7
Parent Item: D3267-043			 37-043*	•			
Parent Item Name: Basket Lid Ass	sembly (Inside)	17.376)/-(14.5			Date: 18/11/2011 t Qty: 1.00	Required Date: 09/12/2011 Required Qty: 1.00
M304TS0.750W.065	Purchased	No		100 f	506.7499	7 7.368	421
M304TS0 750\ 304 SQ Tube .75x,75x.065W	N 065				*	* 39	11/12/07
		Locat	<u>ion</u>	Loc Qty	Loc Code		q
		MATO)18	485.0857585			
			117636	67.9987			
		<	118773	417.087059		-4 .	<u>3C</u>
		WA	110101	6.0667		 -	
		****	118181	6.0667		-	·
		WA00	116267	15.5974906 14.628472			
			116763	0.9690186			
M304EX0.75-16F	Purchased	No		110 . sf	554.2561	4.3 4.526	 316
*M304FX0 75-1 Expanded Metal Flat SS					*	, ,	11/12/07
		Locati	<u>ion</u>	Loc Qty	Loc Code		
		WA		554.2561116			
			117197	102.9036			
			117896	53.3264			
			118153 118248	76.8473 33.0983			
			118597	21.06788			
			118955	82.17			
		<	119180	184.842632		4.52	

Dart Aer	ospace	Ltd
----------	--------	-----

	•								€ *
W/O:			WC	ORK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
	Res	solution:	Disposition	າ:	QA: N/C C	osed:		Date: _	
NCR:			WORK ORDI	ER NON-CONFORM	ANCE (NCF	₹)			
DATE	STEP	Description of NC	Corrective Action Section 8 Initial Action Description				cation	Approval	Approval
	0.2.	Section A	Chief Eng	Action Description Chief Eng	Sign 8 Date		on C	Chief Eng	QC Inspector
									,
									,

QTY -041	QTY -043	PART NUMBER	DESCRIPTION
х		D3267-041	BASKET LID ASSEMBLY (OUTSIDE)
	х	D3267-043	BASKET LID ASSEMBLY (INSIDE)
2		D2327-3	SPACER BUSHING
1		D2506	LABEL PLATE
1		D2512-7	STRUT
2		D2581	MOUNTING BRACKET
	1	D2989-1	STRUT
	1	D2989-2	STRUT
	1	D2989-3	STRUT
	1	D2989-4	STRUT
	2	D2989-5	STRUT
	2	D2989-7	STRUT
1		D2989-9	STRUT
1		D2989-10	STRUT
1		D2989-11	STRUT
1		D2989-12	STRUT
2		D2989-13	STRUT
2		D2989-15	STRUT
	2	D3182-1	HINGE
2	2	D3265-3	STRUT
1		D3266-7	STRUT
2		D3267-1	STRUT
	2	D3442-3	SHIM

SHOP COPY RETURN TO **ENGINEERING UNCONTROLLED COPY** SUBJECT TO AMENDMENT WITHOUT NOTICE
WORK ORDER
NO. 76650 M.L.5

В

1) FRAME MATERIAL: AISI 304/316 SS, 3/4 x 3/4 x 0.065 WALL SQUARE TUBING REF. DART SPEC M304TS0.750W.065 (D2989-3/4/5/11/12/13 CAN BE MADE FROM D2236)

2) MESH MATERIAL: 3/4-16F EXPANDED SS

REF DART SPEC M304EX0.75-16F

3) FINISH: POWDER COAT ENTIRE ASSEMBLY WHITE (REF. 4.3.5.2) PER DART QSI 005 4.3. BLACK ANTI-SKID PAINT INDICATED AREA PER DART QSI 005 4.4. SPRAY PAINT INSIDE SURFACE BLACK PRIOR TO APPLYING ANTI-SKID.

3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED

4) UNITS: INCHES UNLESS OTHERWISE NOTED

5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX

6) IDENTIFICATION: NONE


7) WEIGHT: N/A

8) WELD PER DART QSI 004


A REV.	ADD SHIM UNDE NEW ISSUE	DS BY	05.06.08 04.02.02 DATE			
	DS	BY	DATE			
DRAWN AJS			DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA			

REV.		JESCRIPTION	BY	DATE		
DESIGN DS		DART AEROSPACE LTD				
DRAWN AJS		HAWKESBURY, ONTARIO, CANADA				
CHECKED	PEF	DRAWING NO.		REV. C		
MFG. APPR.	E	D3267	s	HEET 1 OF 3		
APPROVED	M	TITLE		SCALE		
DE APPR.	-44-	BASKET LID ASSEMBLY NT				
DATE OS C	R 15	COPYRIGHT © 2004 BY DART AEROSPACE LTD . THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONCILION THAT IT IS				

Dart Ae	rospace	e Ltd		_				
W/O:			WO	RK ORDER CHANG	GES			
DATE	STEP	PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			81					
		A/A	•					
				•				
				•				
Part No):	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA:	Date: _	
* Resolution:		Disposition:		QA: N/C C	losed:	Date:		
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCI	R)		
		Description of NC		Corrective Action Sec	tion B	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date	& Section C	Chief Eng	QC Inspector
								ø
							,	,
		*						



Dart Ae	rospace L	_td		· (
W/O:		*	WO	RK ORDER CHANGE	S y			
DATE STEP		PROCEDURE CHANGE			Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•				
			,					
Part No	:	PAR #:	Fault Categ	Jory:	NCR: Yes	No DQA:	Date: _	
	Res	solution:	Disposition	l:	QA: N/C CI	osed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMAL	NCE (NCR	3)		
	STEP	Description of NC Section A	Corrective Action Section B			Verification	Approval	Approval
DATE			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
			West to the second seco			,		
:				·				
-								



Dart Ae	rospace	Ltd		•	1	9 4 - 19 ger		e :
W/O:		- A Company of the Co	WO	RK ORDER CHANGES				
DATE STEP		PROCEDURE CHANGE			By	Date < Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						ı		÷
				-				
Part No	•	PAR #:	Fault Categ	ory: 1	ICR: Yes	No DQA:	······································	<u>.</u>
	Re	esolution:	Disposition	:(A: N/C Clo)sed:	Date: _	·
NCR:		V	WORK ORDE	R NON-CONFORMAN	CE (NCR)		1
		Description of NC	Corrective Action Section B			Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
			, i					
						15.14		
			·					
		·						
		4	1 1		1	1	T .	1